



Invignome's Practice page

Instructions

1. Shake your GnomePen thoroughly for ~30seconds.
2. Make sure the stainless tip is clean and if not – wipe it with a kimwipe.
3. Hold the pens using the white tip and touch the slide.
4. Mark your line along the circle at a steady pace.
5. If your GnomePen fails to write it may be too cold – unscrew the white tip (clockwise!) two turns and close it back tightly. It will function flawlessly.
6. Allow the lines to fully dry – we recommend working in a fume hood. It should take less than 30 seconds in fume hood, or roughly a minute on the bench.
7. Store your pen in a dark cool cabinet or drawer.

Good luck with your experiment.

Invignome Team

